

**INTERIOR CORNER MONUMENTATION / AFFIDAVIT OF CORRECTION**

I, Douglas E. Adkins, P.L.S. No 1794 first being duly sworn say that I am the surveyor who surveyed the plat of Tract 1475 – Gray Rock – Phase 4 as originally recorded in Plat Book 22, Page 717, Klamath County Clerk Records and in accordance with ORS 92.070, I have correctly surveyed and marked with proper monuments the interior corners as indicated on said plat, except that the following corrections to said plat are necessary and are as follows:


1. The monument at the most westerly corner common to Lots 52 and 54 could not be set at the corner because of rocks. A reference monument was set North 51°32'27" East 2.00 feet from the corner.
2. The monument at the southeast end of the line designated on the plat as L14, on the southerly side of the flagpole of Lot 54, could not be set at its platted location because of rocks. A reference monument was set North 55° 19'49" West 2.00 feet from corner.

The present fee owner of the property materially affected by this affidavit is Paradise Hill, L.L.C.

Douglas E. Adkins  
Douglas E. Adkins, PLS #1794

Subscribed and sworn to before me this 24 day of February, 2006.

Cherry N. Wolf  
Notary Public for the State Of Oregon  
My Commission Expires 6/30/09



I, Mike Markus, Klamath County Surveyor, do hereby certify that the Interior Corner Monumentation / Affidavit of Correction for Tract 1475 – Gray Rock – Phase 4 has been examined by me and that it complies with requirements of ORS 92.170 and 92.070 (3)(b)

Approved this 13 day of April, 2006,

Mike Markus  
Mike Markus  
Klamath County Surveyor