

NARRATIVE OF RECORD OF SURVEY No. 2569 "Map of Survey in Lot 11, Block 3, Second Addition to Altaront Acres"

- 1. Purpose of survey was to ser boundary corners of a tract of land in Lot 11, Purpose of survey was to set boundary corners of a fract of fame in bed 12, page 164h7 and divide the tract into three parcels and stake the parcel boundary corners.
- Problems encountered were that the distances of the tract's West, East, and South boundaries described in the deed did not agree with the physical Conditions on the ground. The distance of the tract's West boundary plus the distance tie along the West boundary of Lot 11 to the NW corner of Lot 11 conditions on the ground. The distance of the tract's West boundary plus the distance tis along the West boundary of Lot 11 to the NW corner of Lot (139.6 + 279.2 = 418.80 feet) described in the deed does not agree with The plat's distance for the West boundary of Lot 11 of 360.0 feet.
- The Northerly boundary of the said tract was established according to The Northerty boundary of the said tract was established according to Boundary Settlement, Agreement Volume M77, page 19642. This boundary was used as basis of bearing 46 defined in the deed.
- h. The Easterly boundary and Westerly boundary of said tract was established from the location of the North-South fence line that divides Casitas Subdivision on the West from this subdivision (Second Addition to Altement Acres) on the East, and the found 5/8" iron red property corner on the Acres) on the mash, and one round 5/0 from red property corner on one priginal East Bisbee Street right-of-way near the SE corner of Lot 11.

 This 5/8" iron rol was found to fit the tract's Northerly boundary for plat's complete and distance and beging between the fact and complete and distance and dist engle and distance location. The distance and bearing between the East and West boundary was established according to the deed.
 - 5. The Southerly boundary was established as the Northerly right-of-way line
 - The SE corner of Lot 11 was located at the North toe of the Lateral's of the U.S.R.S. Lateral A-3. bank slope and the South side of an existing fence.
 - The SW corner of Lct 11 was located as follows:
- 1. The original iron axle believed to have been set for the SE corner of Casitas Subdivision was found. Measurements showed this axle to be located 1.38 feet Northwesterly along the lateral's right-of-way DE LOCADER 1.30 TEEL NOTHINGESTELLY ALONG THE LABORAL S FIGHT-GIANG Line from this survey's established location of the West boundary
 - The NW property corner of Lot 2 in Casitas Subdivision was found to The NW property corner of Lot 2 in Casitas Subdivision was found of be 0.50 feet longer Westerly than record from the West Boundary of
 - Studies were made to try to use the found iron axle as the Sw corner of Lot 11 but the results proved that it could not be used because it could create a serious angle point somewhere in the West boundary
 - 4. The axle was found to be 20 feet from the centerline of the U.C.R.C. Lateral A-3 and was therefore accepted as a point on the Northerly
 - The South boundary in its final location on the Lateral's Northerly right-of-way line was adjusted to fit the axle as a point on that line.
 - 6. The SW corner of Lot 11 was located at the intersection of the Whot and South boundary of this subdivision. Distances from this Su corner Northerly along the West boundary of this subdivision agrees with the Casitas Subdivision Plat distances.
 - 6. This tract's deed description was re-written to correct and supercede the previous deel Volume M76, page 16447, and this record of survey number was referred to in that deed description.

REGISTERED TATE OF OREGON; COUNTY OF KLAMATH; 55. PROFESSIONAL LAND SURVEYOR and for record at request of Glenn Resirez A.D 1978 a7:16 clock M. on Mayne Church on Page 9560 10th day of May OREGON fully recorded in Vol. H73 of Deeds. Wm D. MILNE, County Class WAYNE C. CHURCH By Demecha y Fac \$15.00

dilum Den D Lamars, PO Box 361 1. in